



This Parts Bulletin details a universal change from a 60 watt (W) coated incandescent light bulb to a 40 W coated incandescent light bulb.

Up until now, Hatco has been using a 60 W safety-coated incandescent light bulb in many foodwarming products to illuminate food holding areas. Unfortunately, 60 W light bulbs with the required quality and safety features have become very difficult to acquire.

Hatco is now transitioning from the 60 W light bulb to a 40 W safety-coated incandescent light bulb. The new 40 W light bulb will fit all of the same applications as the 60 W light bulb and will have the same quality and safety features including:


- Heavy duty filament with multiple supports to absorb vibrations
- Brass base allowing ease of bulb removal from socket
- Safety coating that protects food product from glass breakage.

The shape of the new 40 W light bulb is similar to a standard incandescent light bulb versus the existing 60 W light bulb, which is shaped similar to a large chandelier bulb. Because the wattage of the bulb changes from 60 W to 40 W, the lumens or light output is reduced slightly.


For more information, contact the **Hatco Parts and Service Team** at:

Telephone: 800-558-0607 or 414-671-6350

e-mail: support@hatcocorp.com



Discontinued 60 W Coated Incandescent Light Bulb



New 40 W Coated Incandescent Light Bulb



24 Hour 7 Day Parts and Service
Assistance available in the United States
and Canada by calling 800-558-0607.

HATCO CORPORATION
P.O. Box 340500
Milwaukee, WI 53234-0500 U.S.A.
800-558-0607 414-671-6350
support@hatcocorp.com
www.hatcocorp.com